School or Site	* Project Type or Location	Project Description	Estimated Costs	Design and Fee Costs	Total Estimated Cost
	S.S Sidewalk hazards	There are multiple hazards along student drop off zone and exits to playgrounds. There are sections of concrete missing in a few areas of the sidewalk. The bus lane and the front entry of the school need ADA (American with Disabilities Act) ramps brought up to standards.	\$ 4,083.78	\$ 51.26	\$ 4,135.04
	G.M Roof upgrades	Roof has insulation foam that contains hazardous coatings and adhesives. Sections of the roof need to be removed and replaced.			\$ 265,576.32
Cromer Elementary School (1986-1987)	S.S Gutters and downspouts	There is inadequate drainage for gutters and downspouts. Drainage pipe is broken and exposed by front entry sidewalk and needs to be repaired due to safety hazards.	\$ 2,750.00	\$ 67.65	\$ 2,817.65
(1900-1907)	G.M Plumbing upgrades	Sink ADA insulation is missing or inadequate in restrooms. The water fountains have inadequate ADA covering and need to be replaced.	\$ 2,268.00	\$ 55.79	\$ 2,323.79
	G.M Fire lane pavement	The asphalt located in the fire lane has deteriorated in multiple areas due to inadequate drainage. A number of sections of asphalt needs to be replaced in order to reduce hazards.	\$ 13,198.68	\$ 1,380.58	\$ 14,579.26
	S.S Front entry interior upgrades	The existing main office does not have an adequate view of front entry doors. The staff cannot view incoming visitors. The office will need to be remodeled in order to accommodate staff view of entry doors.	\$ 60,750.00		
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$ 35,500.00	\$ 92.14	\$ 35,592.14
DeMiguel Elementary	E.E Mechanical upgrade	The existing EMS (Energy Management System) system in the new wing has different control			
School		software than the remainder of the building. In order to efficiently control the building EMS, it will need to be upgraded to the new Delta control			
(1989)		system.	\$ 48,600.00	\$ 1,195.56	\$ 49,795.56

<sup>\*</sup>S.S. Safety and Security; G.M. General Maintenance; E.E. Energy Efficiency; B.R. Bus Replacement; F.E. Furniture and Equipment

School or Site	* Project Type or Location	Project Description	Esti	mated Costs	De	sign and Fee Costs	e Total Estima Cost	
							_	
	S.S Sidewalk hazards	There are multiple hazards located in the playground area. The front parking lot has a broken concrete drainage scupper that needs to						
	G.M Interior carpet	be replaced. The original carpet (23 years) is deteriorating in	\$	2,856.60	\$	70.27	\$	2,926.87
	S.W. Menor darpet	hallways and classrooms and needs to be replaced.	\$	215,987.00	\$	5,264.08	\$	221,251.0
DeMiguel Elementary	G.M Interior upgrades	The hallways and classrooms need drywall repairs and paint. There are a few sections of the	Ť		Ť	,	<u> </u>	
School		building that have settled, and inadequate expansion joints have caused the drywall to						
(1989)		crack.	\$	145,806.25	\$	3,586.83	\$	149,393.0
	S.S Parking lot pavement	The east parking lot is deteriorated and has multiple potholes. The front parking lot and fire lane are beginning to show signs of deterioration in multiple areas. There is also inadequate drainage, causing the asphalt to deteriorate more so. The sidewalk located adjacent to the bus lane has cracked in multiple areas, causing hazards.						
	C.M. Drainaga by	The outerior steire leasted by symposium reads	\$	398,871.00	\$	41,721.91	\$	440,592.9
	G.M Drainage by gymnasium	The exterior stairs located by gymnasium needs to be sealed correctly. During precipitation, water enters gym by exterior stairs and is damaging gym floor.	\$	5,136.00	\$	126.35	\$	5,262.3
	G.M Gymnasium floor	The gymnasium floor will need to be repaired in areas that have been water damaged. The existing gymnasium floor has bubbled in areas that have gotten wet. The cove base and drywall will also need to be repaired in areas that have been water damaged.	\$	14,589.78		358.91	\$	14,948.6
	E.E Electrical upgrades	The exterior light wall packs need to be upgraded to energy efficient fixtures and in accordance with the electrical standards. The existing fixtures are currently low pressure sodium.	*	,	<b>,</b>	333.31	*	,5 15.0
		currently low pressure socium.	\$	9,660.00	\$	237.64	\$	9,897.6

School or Site	* Project Type or Location	Project Description	Estim	nated Costs	Des	sign and Fee Costs	Tot	al Estimated Cost
DeMiguel Elementary	S.S Front entry interior upgrades	The existing main office does not have an adequate view of front entry doors. The staff			П			
School		cannot view incoming visitors. The office will need to be remodeled in order to accommodate staff						
(1989)		view of entry doors.	\$	52,650.00	\$	5,507.19	\$	58,157.19
	G.M Plumbing upgrades	The existing pipes located in the boiler room have deteriorated due to age. An allowance will be						
		included to remove and replace as needed.	\$	5,940.00	\$	712.80	\$	6,652.80
	G.M Playground upgrades	Softfall material is needed at playgrounds for fall zone requirements. Any remaining railroad ties						
		need to be removed and replaced with softfall retention material.	\$	12,960.00	\$	1,036.80	\$	13,996.80
Kinsey Elementary	S.S Front entry interior upgrades	The existing main office does not have an adequate view of front entry doors. The staff						
School		cannot view incoming visitors. The office will need to be remodeled in order to accommodate staff						
(1958-1985)		view of entry doors.	\$	54,000.00	\$	5,648.40	\$	59,648.40
,	G.M Sidewalk hazards	ADA access needs to be reviewed for playground access. ADA access is needed by bus drop off	·	,		,	•	,
		lane and entry to building.	\$	6,810.00	\$	167.53	\$	6,977.53
	E.E Mechanical upgrade	The existing unit ventilators need to be evaluated. The modulating valves need to be evaluated in		,	·			,
		order to increase efficiency.	\$	3,920.00	\$	96.43	\$	4,016.43
	G.M Parking lot pavement	The existing bus and parent pick up and drop off needs to be redesigned. The parking lot becomes too congested during hours of pick up and drop off. The asphalt is also deteriorating and needs to						
		be replaced.	\$	275,425.92	\$	28,809.55	\$	304,235.47
	E.E Window upgrades	The gymnasium needs Kalwall windows in order to add natural day lighting to area. The Kalwall windows reduce temperature fluctuations during						
	C.M. Intovice	winter and summer months.	\$	6,076.48	\$	149.48	\$	6,225.96
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$	35,500.00	\$	92.14	\$	35,592.14

School or Site	* Project Type or Location	Project Description	Esti	mated Costs	Des	sign and Fee Costs	Tot	al Estimated Cost
	E.E Window upgrades	The gymnasium needs Kalwall windows in order						
	1,2,000	to add natural day lighting to area. The Kalwall						
		windows reduce temperature fluctuations during						
		winter and summer months.	\$	9,034.63	\$	222.25	\$	9,256.88
Killip Elementary	S.S Sidewalk hazards	The front entry sidewalk and ramp have multiple						
		hazards due to separation and deterioration of						
School		concrete. The north sidewalk to playground needs						
SCHOOL		to be replaced due to deterioration from ice						
		damage. The front entry handrails also need to be						
(1948-1985)		replaced and brought up to new standards.	\$	7,840.00	\$	192.86	\$	8,032.86
	G.M Door hardware	The existing doors and hardware located at north						
		entry need to be reviewed and replaced as						
	upgrades	needed.	\$	10,528.96	\$	259.01	\$	10,787.97
	G.M Drainage by north	The existing concrete drain located by the north						
		doors is not draining properly and needs to be						
		reviewed in order to prevent water and ice						
	doors	accumulation.	\$	3,080.00	\$	75.77	\$	3,155.77
	G.M Interior carpet	Carpet contingency is needed in order to replace					_	
		any damaged carpet.	\$	35,500.00	\$	92.14	\$	35,592.14
	G.M Parking lot	The existing parking lots need to be re-sealed						
	pavement	and re-striped in order to maintain asphalt	_		_	0.4=4.00	_	
		surface.	\$	53,760.00	\$	6,451.20	\$	60,211.20
Knoles Elementary	G.M Roofing upgrades	The existing roof has asphalt shingles, no ice and						
		water shield, and very little or no heat tape. The						
		roof sections 2 and 3 of existing roof are due for						
School		replacement per the District's evaluation plan.						
		Expansion joints will need to be installed on new						
		roof in order to prevent any buckling.						
(1986-1987)			\$	234,752.00	\$	5,774.90	\$	240,526.90

School or Site	* Project Type or Location	Project Description	Estimated Costs	De	esign and Fee Costs	To	tal Estimated Cost
	S.S Gutters and downspouts	The roof gutters and downspouts are inadequate on the north end of the building. There are multiple leaks in existing system. There needs to be repair and/or replacement in order to eliminate any hazards during winter months.	\$ 5,457.00	\$	134.24	\$	5,591.24
<b>Knoles Elementary</b>	E.E Mechanical	The existing unit ventilators need to be reviewed					·
School	upgrade	and replaced. The existing system is obsolete. The modulating valves need to be changed in order to increase efficiency. The EMS system at this site will need to be upgraded to new software					
(1986-1987)		requirements.	\$ 121,746.00	\$	1,497.48	\$	123,243.48
	G.M New generator	The existing generator has deficient parts and needs to be replaced with a gas fired generator. The new generator needs to be evaluated in regards to the amount of electric capacity needed during any power outages.	\$ 91,800.00	\$	2,258.28	\$	94,058.28
	E.E Window upgrades	The library clerestory windows are not fully sealed and are causing condensation between window panels. This causes a loss of heat during winter months, because they are located at the ceiling elevation height. New double pane windows are needed.	\$ 17,237.11	\$	2,068.45	\$	19,305.57
	G.M Parking lot pavement	The existing parking lot located by the front entry and bus lane is beginning to deteriorate due to age and needs to be replaced.	\$ 115,422.75		2,839.40	\$	118,262.15
	S.S Electrical upgrades	The gymnasium light switches are located in the electrical panel across the room. For safety reasons, new light switches need to be installed by entry doors.	\$ 2,800.00		68.88		2,868.88
	G.M Plumbing upgrades	The existing restroom sinks need ADA insulation installed. There are multiple sink fixtures that need to be replaced in restrooms. The drinking	,				,
		fountains need ADA insulation.	\$ 53,760.00	Φ	1,322.50	Ą	55,082.50

School or Site	* Project Type or Location	Project Description	Esti	mated Costs	De	sign and Fee Costs	Total Estimated Cost	
Knoles Elementary	S.S Front entry interior upgrades	The existing main office does not have an adequate view of front entry doors. The staff						
School		cannot view incoming visitors. The office will need to be remodeled in order to accommodate staff						
(1986-1987)		view of entry doors.	\$	157,500.00	\$	16,474.50	\$	173,974.50
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$	35,500.00	\$	92.14	\$	35,592.14
	G.M Playground upgrades	Softfall material is needed at playgrounds for fall zone requirements. Any remaining railroad ties need to be removed and replaced with softfall						
		retention material.	\$	12,960.00	\$	1,036.80	\$	13,996.80
Leupp Elementary	G M. Electrical ungrades	A gas fired generator needs to be installed in						
School	C.W. Electrical appraises	order to handle the electrical needs during power outages. The site has multiple power outages						
(2004)		during winter and summer months.	\$	95,200.00	\$	2,341.92	\$	97,541.92
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$	35,500.00	\$	92.14	\$	35,592.14
Marshall Elementary	E.E Window upgrades	The gymnasium needs Kalwall windows in order						
School	L.L Willdow apgrades	to add natural day lighting to area. The Kalwall windows reduce temperature fluctuations during						
(1952-1986)		winter and summer months.	\$	16,642.73	\$	409.41	\$	17,052.14
,	G.M Parking lot pavement	The existing parking lot located by the front entry and north end of the building is beginning to deteriorate due to age and needs to be replaced.	·	,	•		·	,
			\$	244,750.00	\$	6,020.85	\$	250,770.85
	S.S Sidewalk hazards	An ADA sidewalk is needed to front entry doors.  Multiple hazards are present in playground walkways. Transitions from asphalt to concrete						
		have separated and are causing hazards.	\$	9,114.00	\$	224.20	\$	9,338.20
	S.S Site work	The existing railroad ties need to be removed from playground, there are multiple hazards. The retaining wall located in the playground areas						
		need top caps re-glued.	\$	1,394.40	\$	34.30	\$	1,428.70

School or Site	* Project Type or Location	Project Description	Estim	nated Costs	Des	sign and Fee Costs	Tot	tal Estimated Cost
Marshall Elementary	S.S Modular building upgrades	The ramps for the modular buildings are deteriorating, the handrails are bowing, and the						
School		wood is beginning to split in multiple areas. The existing modular buildings need to be fully						
(1952-1986)		evaluated.	\$	57,200.00	\$	619.92	\$	57,819.92
	S.S Door hardware	The existing doors located by the courtyard need to be replaced. The doors have a 1" transition that is causing a hazard between doors.						
	upgrades		\$	12,880.00	\$	316.85	\$	13,196.85
	E.E Mechanical upgrade	The existing unit ventilators need to be evaluated. The modulating valves need to be evaluated in						·
		order to increase efficiency.	\$	3,920.00	\$	96.43	\$	4,016.43
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$	35,500.00	\$	92.14	\$	35,592.14
	G.M Playground upgrades	Softfall material is needed at playgrounds for fall zone requirements. Any remaining railroad ties need to be removed and replaced with softfall						
		retention material.	\$	12,960.00	\$	1,036.80	\$	13,996.80
Puente de Hozho	G.M Sidewalk hazards	The sidewalk and concrete stairs that access the						
Elementary School		north parking lot need to be widened for pedestrian traffic. New handrails will be needed in						
(1964-1997)		areas that have a fall zone.	\$	4,480.00	\$	110.21	\$	4,590.21
	G.M Parking lot pavement	The north and south parking lots are deteriorating and causing multiple hazards throughout. There						
		are also multiple potholes located in the parking lots.	\$	253,792.00	\$	6,243.28	\$	260,035.28
	G.M Plumbing upgrades	There is exposed piping that needs to be properly covered and secured in the teacher lounge. ADA insulation is also needed for plumbing pipes.						
			\$	2,520.00	\$	61.99	\$	2,581.99
	G.M Interior carpet	New abrasive action carpet is needed in entryways. The existing carpet tiles are		•			•	•
		deteriorating due to wear.	\$	2,451.08	\$	60.30	\$	2,511.38

School or Site	* Project Type or Location	Project Description	Estimated Costs	Design and Fee Costs	Total Estimated Cost
Puente de Hozho Elementary School (1964-1997)	E.E Mechanical upgrade	A new exhaust fan is needed for server room located in library. The area is now cooled 24 hours a day with a non-energy efficient fan.	\$ 5,400.00	\$ 132.84	\$ 5,532.84
	G.M Roofing upgrades	The remaining roof sections need to be replaced due to age and deterioration. The existing roof has asphalt shingles, built up roofing, no ice and water shield, and very little or no heat tape.	\$ 329,808.00	\$ 8,113.28	\$ 337,921.28
Sechrist Elementary School	E.E Mechanical upgrade	The existing unit ventilators need to be evaluated. The modulating valves need to be evaluated in			
(1964-1985)	E.E Window upgrades	order to increase efficiency. The gymnasium needs Kalwall windows in order	\$ 3,920.00	\$ 96.43	\$ 4,016.43
		to add natural day lighting to area. The Kalwall windows reduce temperature fluctuations during winter and summer months.	\$ 10,342.27	\$ 254.42	\$ 10,596.69
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$ 35,500.00	\$ 92.14	\$ 35,592.14
	G.M Interior upgrades	Multiple ceiling tiles located in the main hallways are falling down. The ceiling tiles will need to be removed and replaced.	\$ 8,332.80	\$ 666.62	\$ 8,999.42
Thomas Elementary	E.E Window upgrades	The gymnasium needs Kalwall windows in order			
School	L.L William appraces	to add natural day lighting to area. The Kalwall windows reduce temperature fluctuations during	f 40 040 70	<b>*</b> 400.44	¢ 47.052.44
(1966-1998)	G.M Interior upgrades	winter and summer months.  Multiple ceiling tiles located in the main hallway are falling down. The ceiling tiles need to be removed and replaced with new 1X1 ceiling tile.	\$ 16,642.73 \$ 6,704.00	\$ 409.41 \$ 164.92	
	G.M Site work	The retaining wall caps need to be re-installed as needed by playground and front entry walkways.	\$ 4,082.40		

School or Site	* Project Type or Location	Project Description	Estimated Costs	De	sign and Fee Costs	То	tal Estimated Cost
	S.S Modular building upgrades	The modular buildings have wooden ramps that need to be replaced. They are separating and causing hazards.	\$ 23,276.00	\$	572.59	\$	23,848.59
Thomas Elementary	S.S Handrail upgrades		Ψ 25,270.00	Ψ	372.00	Ψ	20,040.00
School	C.C. Hariaran apgrados	have fall zones on each side of the walkway. The handrails need to be installed in accordance with					
(1966-1998)		standards.	\$ 6,282.50	\$	154.55	\$	6,437.05
	G.M Nurse's office upgrades	The existing Nurse's office has inadequate room. The ADA requirements need to be addressed during any renovations.	\$ 20,250.00	\$	2,118.15	\$	22,368.15
	G.M Roofing upgrades	Remove and replace roof sections that are deteriorating. The existing whirly birds will be reviewed, some may be deleted. The existing roof has asphalt shingles, built up roofing, no ice and			,	•	,
		water shield, and very little or no heat tape.	\$ 195,552.00	\$	4,810.58	\$	200,362.58
	G.M Playground upgrades	Softfall material is needed at playgrounds for fall zone requirements. Any remaining railroad ties need to be removed and replaced with softfall retention material.	\$ 12,960.00	\$	1,036.80	\$	13,996.80
					·		
Subtotal for Elementar	y Schools		\$ 4,108,574.85	\$	186,504.77	\$	4,295,079.62
							_
Mount Elden Middle School (1958-1996)	G.M Interior carpet	The carpet (16 years) is worn and deteriorating. The carpet needs to be replaced throughout hallways and classrooms. Existing tile floors will also need to be replaced.	\$ 333,630.55	\$	8,207.31	\$	341,837.86
(1333 1333)	S.S Gymnasium floor	The gymnasium floor has multiple areas that have been damaged due to expansion and contraction of floor. The areas that are damaged are causing hazards. The gymnasium floor will need to be replaced, and expansion joints will need to be installed.	\$ 122,749.56		3,019.64		125,769.20

School or Site	* Project Type or Location	Project Description	Estim	nated Costs	Design and Fee Costs		To	tal Estimated Cost
Mount Elden Middle	E.E Mechanical upgrade	The Heating, Ventilation, Air/Conditioning (HVAC) controls and system needs to be reviewed. The						
School		system will need to be rebalanced. The existing boiler needs to be reviewed and possibly upgraded. The EMS software will need to be						
(1958-1996)		upgraded.	\$	280,000.12	\$	29,288.01	\$	309,288.13
	G.M Handrail upgrades	The existing handrail located by seminar room is not properly anchored into concrete and is damaged. The handrail needs to be repaired as needed.	\$	3,360.00	\$	82.66	\$	3,442.66
	S.S Sidewalk hazards	The sidewalk adjacent to 4th street needs to be replaced in multiple areas due to deterioration. The sidewalk needs to be replaced in order to reduce any hazards.	\$	7,532.00	\$	136.09	\$	7,668.09
	G.M Roofing upgrades	The built up roofing over the pool needs to be replaced. Existing roof is bubbling in areas and causing roof leaks.	\$	71,904.00	\$	1,768.84	\$	73,672.84
	G.M Roofing upgrades	Roof needs to be replaced in section 1, 2, 3, 4, and 5 (classroom wings and locker room area). The existing roof has asphalt shingles, built up roofing, no ice and water shield, and very little or no heat tape.	\$	965,440.00	\$	23,749.82		989,189.82
	E.E Electrical upgrades	A 600 amp distribution panel needs to be replaced. The electrical panel is located in a block wall and needs to be relocated and upgraded to a		13,440.00	\$	330.62	\$	
	E.E Lighting upgrades	higher efficiency panel.  The exterior light poles are damaged due to snow and wind loads. These light fixtures need to be replaced with energy efficient fixtures and in accordance with standards. Other exterior light wall packs need to be upgraded to energy efficient fixtures. Any and all fixtures need light sensors installed for efficiency.	\$	65,000.00		1,239.84		13,770.62 66,239.84

School or Site	* Project Type or Location	Project Description	Estimated Costs	Design and Fee Costs	Total Estimated Cost
Mount Elden Middle	G.M Interior upgrades	The existing classrooms and hallways need to be			
		re-designed for safety and accessibility. The main			
		staircase in hallway needs to be evaluated for			
School		ADA compliance. The existing building has many			
		un-aligned hallways, which cause safety hazards			
(1958-1996)		for students and vandalism.	\$ 1,626,337.00	\$ 170,114.85	\$ 1,796,451.85
(1000 1000)	F.E Interior upgrades	Furniture and equipment allowance (\$300,000.00)	Ψ :,σ=σ,σσ::σσ	Ψ 11 0,11 1100	Ψ 1,1 00, 10 1100
		will be added for renovation project.	\$ 298,000.00	\$ 2,000.00	\$ 300,000.00
	G.M Interior upgrades	The existing locker room needs interior upgrades,			
		such as plumbing, wall, and ceiling repairs. The			
		existing lockers will also be replaced with new	<b>4500000</b>	<b>40.404.00</b>	<b>470 004 00</b>
	C.M. Interior unaredea	lockers. The interior insulation needs to be reviewed and	\$ 156,800.00	\$ 16,401.28	\$ 173,201.28
	G.M Interior upgrades		\$ 92,863.36	\$ 2,284.44	¢ 05 147 90
Sinagua Middle School	E E Mochanical	installed as required for walls and ceilings.  The existing unit ventilators need to be evaluated.	\$ 92,863.36	Φ 2,204.44	\$ 95,147.80
Sinagua Middle School	upgrade	The modulating valves need to be evaluated in			
	apgrade	order to increase efficiency. The mechanical coils			
		(48) need to be replaced as needed throughout			
(1989)		building.	\$ 77,880.00	\$ 144.65	\$ 78,024.65
, ,	G.M Site work	The existing sidewalk located by the Little Ropers	,		,
		program needs to have proper drainage installed.	\$ 3,920.00	\$ 96.43	\$ 4,016.43
	G.M Parking lot	The remainder of the front entry parking lot needs			
	pavement	to be re-paved. The kitchen loading and			
		unloading zone and west parking lot need to be re-			
		paved, because the existing lots are deteriorating.	\$ 537,625.00	\$ 56,235.58	\$ 593,860.58

School or Site	* Project Type or Location	Project Description	Estimated Costs		Design and Fee Costs	То	tal Estimated Cost
Sinagua Middle School	E.E Lighting upgrades	The exterior light poles are damaged due to snow and wind loads. These light fixtures need to be replaced with energy efficient fixtures and in accordance with standards. Other exterior light		Ī			
(4000)		wall packs need to be upgraded to energy efficient fixtures. Any and all fixtures need light	¢ 400,000,0		Ф 0.470.00	·	402 270 60
(1989)	S.S Handrail upgrades	sensors installed for efficiency.  The existing interior staircase handrails need to be extended in accordance with new standards.	\$ 100,800.0 \$ 28,000.0		\$ 2,479.68 \$ 688.80	\$	103,279.68 28,688.80
	G.M Door hardware	An ADA button is needed in 600 double doors in order for students to access the bus loading and	Ф 00000		¢ 00.40	Ф.	4.040.40
	upgrades	drop off area.	\$ 3,920.0	U	\$ 96.43	\$	4,016.43
	G.M Plumbing upgrades	The existing interior drinking fountains need ADA insulation in accordance to standards. The drinking fountain walls need repairs due to fixture	ф 4.007.5		Ф 20.70	Ф.	4 227 20
	G.M Mechanical upgrade	replacement or damaged fixtures.  The existing hallway mechanical systems need covers replaced due to damage. The damaged areas are exposing piping in various areas in hallways.	\$ 1,207.5 \$ 23,100.0		\$ 29.70 \$ 568.26	\$	1,237.20 23,668.26
	S.S Interior carpet	The interior carpet (20 years) and tile needs to be	20,100.0		<b>*</b>	Ψ	
		replaced. The thresholds between classrooms in					
		hallways are separating and becoming hazards.					
		The metal expansion plates in hallways need to be leveled in order to prevent hazards in hallways.	\$ 577,162.4	4	\$ 14,198.20	\$	591,360.64
	G.M Drainage in	There is inadequate drainage in a central	Ψ 377,102.4	+	Ψ 14,190.20	Ψ	391,300.04
		courtyard that is causing precipitation to					
		deteriorate brick walls. Proper drainage is needed					
	Courtyard	in order to prevent water from entering building.	\$ 15,120.0	0	\$ 1,581.55	\$	16,701.55

School or Site	* Project Type or Location	Project Description	Estim	ated Costs	Design and Fee Costs		Total Estimated Cost	
Sinagua Middle School	S.S Front entry interior upgrades	The existing main office does not have an adequate view of front entry doors. The staff cannot view incoming visitors. The office will need to be remodeled in order to accommodate staff						
(1989)		view of entry doors.	\$	56,720.80	\$	5,932.99	\$	62,653.79
Subtotal for Middle Sch	ools		\$ 5	,462,512.33	\$	340,675.67	\$	5,803,188.00
				,	·	·		,
Christensen Complex:	S.S Sidewalk hazards	The existing sidewalk located by the front entry						
(4070 4007)		has multiple pieces that are separating and will						
(1970-1987)		need to be removed and replaced as needed in order to eliminate any hazards.	\$	1,890.00	\$	46.49	\$	1,936.49
New Start, TAPP,	G.M Roofing upgrades	The existing built up roof needs to be replaced in	Ψ	1,000.00	Ψ	10.10	Ψ	1,000.10
	0 10	section 1 and 2. The HVAC units will need to be						
Family Resource		resealed when roof is completed. The existing						
Ocaston		roof has built up roofing, no ice and water shield,		050 000 00	_	0.004.00	_	007 000 00
Center		and very little or no heat tape.	\$	358,992.00	\$	8,831.20	\$	367,823.20
	S.S Sidewalk hazards	The existing sidewalk located by Izabel Street has						
	O.O. Oldowalk Hazardo	multiple hazards and needs to be replaced.	\$	6,040.00	\$	123.98	\$	6,163.98
Coconino High School	G.M Interior upgrades	The existing auditorium needs new aisle lighting, handrails by stage, seating upgrades, and carpet. The new renovations will need to be in accordance with building codes and standards.	Ψ	0,040.00	Ψ	120.30	Ψ	0,100.00
(1966-1988)		g and the state of	\$	410,880.00	\$	11,598.05	\$	422,478.05
	F.E Interior upgrades	Furniture and equipment allowance (\$50,000.00) will be added for auditorium project.	\$	48,000.00	\$	2,000.00	\$	50,000.00
	G.M Plumbing	The existing plumbing fixtures located in the		,		,		,
	upgrades	restrooms and science labs need to be upgraded	_				_	
		to new standards.	\$	14,580.00	\$	358.67	\$	14,938.67

School or Site	* Project Type or Location	Project Description	Estimated Costs	Design and Fee Costs	Total Estimated Cost
Coconino High School	S.S Handrail upgrades	The existing athletic field stadium needs handrails installed in center aisles. The students/staff have no handrails on stairs to press box. The new			
(1966-1988)		handrails will need to be installed in accordance to standards.	\$ 13,440.00	\$ 330.62	\$ 13,770.62
	S.S Handrail upgrades	The existing interior staircase handrails need to be extended in accordance with new standards.	\$ 27,400.00	\$ 674.04	\$ 28,074.04
	E.E Lighting upgrades	The exterior light poles are damaged due to snow and wind loads. These light fixtures need to be replaced with energy efficient fixtures and in accordance with standards. Other exterior light wall packs need to be upgraded to energy efficient fixtures. Any and all fixtures need light			
		sensors installed for efficiency.	\$ 100,720.00	\$ 2,231.71	\$ 102,951.71
	G.M Fire alarm upgrades	The existing fire alarm system needs sprinkler heads and smoke detectors replaced/repaired.	\$ 44,800.00	\$ 1,102.08	\$ 45,902.08
	G.M Interior carpet	Carpet contingency is needed in order to replace any damaged carpet.	\$ 35,500.00	\$ 92.14	\$ 35,592.14
Flagstaff High School (1934-1988)	G.M Roofing upgrades	Remove and replace roofing sections 5, 6, 7, 11, 17, and 18. The existing roof has asphalt shingles, built up roofing, no ice and water shield, and very little or no heat tape.	\$ 683,640.00	\$ 16,817.54	\$ 700,457.54
(130111303)	G.M Interior upgrades	The main auditorium, last changes 1970, needs to be brought up to ADA access standards. New seating, flooring, wall, and ceiling repairs are needed. Electrical and HVAC requirements will be upgraded to conform to standards.	\$ 900,000.00	\$ 130,750.00	\$ 1,030,750.00
	F.E Interior upgrades	The main auditorium and partial science labs will have a furniture and equipment allowance (\$300,000.00) added for renovation projects.	\$ 298,000.00	\$ 2,000.00	
	S.S Interior upgrades	The existing main auditorium stage curtain is torn and is a safety concern and a fire hazard.	\$ 58,320.00	,	\$ 59,754.67


School or Site	* Project Type or Location	Project Description	Estimated Costs	Design and Fee Costs	Total Estimated Cost	
	E.E Mechanical upgrade	The existing HVAC system is insufficient in parts of the auditorium wing and needs to be reviewed and upgraded as needed. Two of the four units located in the auditorium are inoperable. The controls will also be evaluated and possibly				
		replaced.	\$ 85,000.00	\$ 1,045.50	\$ 86,045.50	
	G.M Sidewalk hazards	The existing sidewalk located by the auto shop and east entry needs to be reviewed for proper drainage. Hydronic heating options will be also be reviewed at this time.	\$ 93,744.00	\$ 2,306.10	\$ 96,050.10	
Flagstaff High School	G.M Plumbing	The existing plumbing fixtures for auditorium	,	,	, -	
(1934-1988)	upgrades	restrooms, library restrooms, and science labs need to be reviewed and upgraded in accordance with new standards.	\$ 37,587.20	\$ 924.65	\$ 38,511.85	
	E.E Lighting upgrades	The existing light fixtures need to be fully upgraded from T-8 fixtures to T-12 or T-5 fixtures in classrooms, offices, hallways, gymnasiums, and storage areas in accordance with new standards. Light sensors for energy efficiency will need to be added in areas where necessary.	\$ 28,672.00	\$ 705.33	\$ 29,377.33	
	E.E Lighting upgrades	The exterior light poles are damaged due to snow and wind loads. These light fixtures need to be replaced with energy efficient fixtures and in accordance to standards. Other exterior light wall packs need to be upgraded to energy efficient fixtures. Light sensors will need to be added in areas needed for energy efficiency.	\$ 80,640.00	\$ 1,983.74	\$ 82,623.74	
	G.M Parking lot pavement	The existing west parking lots are deteriorating, and the bus lane has multiple potholes that need replacement/repair.	\$ 200,000.00	\$ 125,520.00	\$ 325,520.00	
	G.M Interior carpet	The remaining original carpet (25 years) is deteriorating in hallways and classrooms and needs to be replaced.	\$ 262,500.00			

School or Site	* Project Type or Location	Project Description	Estimated Costs		Estimated Costs		De	sign and Fee Costs	To	otal Estimated Cost
Subtotal for High School	 ols		\$	3,790,345.20	\$	342,376.51	\$	4,132,721.71		
<b>J</b>			Ť		*	, , , , , , , , , , , , , , , , , , , ,	Ť	, - ,		
District Office Building	S.S Sidewalk hazards	The existing sidewalk located at the district office entry has deteriorated in multiple areas. Remove and replace as needed in order to eliminate								
(1989)		hazards.	\$	1,512.00	\$	37.20	\$	1,549.20		
	E.E Mechanical	The EMS system at this site will need to be								
	upgrade	upgraded to new software requirements. The	φ.	22.450.00	φ.	2 500 00	φ.	25 046 00		
	E.E Lighting upgrades	existing EMS is a pneumatic system.  The existing light fixtures need to be fully	\$	32,450.00	\$	2,596.00	\$	35,046.00		
	L.L Lighting upgrades	upgraded from T-8 fixtures to T-12 or T-5 fixtures in offices, hallways, and storage areas in accordance with new standards. Light sensors will need to be added in areas needed for energy								
		efficiency.	\$	43,815.62	\$	1,077.86	\$	44,893.48		
Subtotal for District Off	l ice Buildina		\$	77,777.62	\$	3,711.06	\$	81,488.68		
			Ť	,	Ť	0,111100	_	01,100100		
Maintenance (1992)/ Transportation (1958)/	E.E Warehouse Lighting upgrades	The existing light fixtures need to be fully upgraded from T-8 fixtures to T-12 or T-5 fixtures in offices, hallways, and storage areas in accordance with new standards. Light sensors will need to be added in areas needed for energy								
Warehouse (1986)		efficiency.	\$	87,631.24	\$	2,155.73	\$	89,786.97		
	E.E Maintenance Lighting upgrades	The existing light fixtures need to be fully upgraded from T-8 fixtures to T-12 or T-5 fixtures in offices, hallways, and storage areas in accordance with new standards. Light sensors will need to be added in areas needed for energy efficiency.	\$	47,320.87	\$	1,164.09	\$	48,484.96		

School or Site	* Project Type or Location	Project Description	Estimated Cost			Design and Fee Costs		Design and Fee Costs		_		tal Estimated Cost
Maintenance (1992)/	E.E Transportation Lighting upgrades	The existing light fixtures need to be fully upgraded from T-8 fixtures to T-12 or T-5 fixtures										
Transportation (1958)/		in offices, hallways, and storage areas in accordance with new standards. Light sensors will need to be added in areas needed for energy										
Warehouse (1986)		efficiency.	\$ 70,560.0	00	\$	1,735.78	\$	72,295.78				
	E.E Transportation Lighting upgrades	The exterior light poles are damaged due to snow and wind loads. These light fixtures need to be replaced with energy efficient fixtures and in accordance with standards. Other exterior light wall packs need to be upgraded to energy efficient fixtures. Any and all fixtures need light										
		sensors installed for efficiency.	\$ 85,002.3	30	\$	2,091.06	\$	87,093.36				
Subtotal for Maintenand	 ce/Transportation/Wareh	nouse	\$ 290,514.4	11	\$	7,146.66	\$	297,661.07				
Oubtotal for Maintenant			Ψ 230,014		Ψ	7,140.00	Ψ	201,001101				
Pupil Transportation Vehicles	B.R Bus Replacement	An adequate school bus replacement schedule is necessary for student transportation safety.	\$ 1,876,000.0	00	\$	31,881.60	\$	1,907,881.60				
Subtotal for Pupil Trans	sportation Vehicles	T	\$ 1,876,000.0	00	\$	31,881.60	\$	1,907,881.60				
General District wide	G.M. Material Testing	Material testing is required by Arizona laws and regulations; therefore, the District must comply and provide for maximum student safety. Material										
Safety and Alternative		testing reports are generated by the testing companies and filed for district use.										
Energy Solutions			\$ 51,000.0	00	\$	6,120.00	\$	57,120.00				

School or Site	* Project Type or Location	Project Description	Estimated Costs		Estimated Costs						То	otal Estimated Cost
General District wide		A new photovoltaic system can be used to generate electricity at a school site and operate										
Safety and Alternative		year around, providing the district with energy savings and rebates. This will provide relief to the										
Energy Solutions		M&O budget.	\$	2,400,000.00	\$	104,600.00	\$	2,504,600.00				
Subtotal for General Di	 strict wide Safety and Al	ternative Energy Solutions	\$	2,451,000.00	\$	110,720.00	\$	2,561,720.00				
TOTAL Estimated Co	ost		\$	18,056,724	\$	1,023,016	\$	19,079,741				

# Flagstaff Unified School District #1 Summary of Projects by Categories for Facilities, Grounds, and Bus Replacement 2013-2019



Category	Estim	Estimated Allocation by Category							
S.S Safety and Security	\$	1,865,309							
G.M General Maintenance	\$	10,622,740							
E.E Energy Efficiency	\$	4,033,810							
B.R Bus Replacement	\$	1,907,882							
F.E Furniture and Equipment	\$	650,000							
Total Estimated Costs for Facilities,									
Grounds, and Bus Replacement	\$	19,079,741							

#### Flagstaff Unified School District #1 Summary of Projects by School and Site

	Current 2006 Bond	Project Totals by Location
Cahaal ay Cita	Expenditures and	for 2013-2019
School or Site	Encumbrances by Location	TOT 2013-2019
Christensen Elementary School	\$ 73,598	\$ -
Cromer Elementary School	\$ 918,145	\$ 392,129
DeMiguel Elementary School	\$ 827,211	\$ 972,875
Kinsey Elementary School	\$ 1,287,573	\$ 416,696
Killip Elementary School	\$ 1,124,093	\$ 127,037
Knoles Elementary School	\$ 1,268,800	\$ 882,502
Leupp Elementary School	\$ 10,150	\$ 133,134
Marshall Elementary School	\$ 934,781	\$ 403,212
Puente de Hozho Elementary School	\$ 466,620	\$ 613,173
Sechrist Elementary School	\$ 1,366,303	\$ 59,205
South Beaver Elementary School	\$ 540,394	\$ -
Thomas Elementary School	\$ 1,073,088	\$ 295,117
Flagstaff Middle School	\$ 758,831	\$ -
Mount Elden Middle School	\$ 1,696,059	\$ 4,027,331
Sinagua Middle School	\$ 435,751	\$ 1,775,857
Christensen Complex	\$ 552,013	\$ 369,760
Coconino High School	\$ 10,439,467	\$ 719,871
Flagstaff High School	\$ 15,690,192	\$ 3,043,091
Sinagua High School	\$ 3,116,406	\$ -
District Office Building *	\$ 1,195,209 *	\$ 81,489
Maintenance/Transportation/Warehouse	\$ 956,284	\$ 297,661
Pupil Transportation Vehicles	\$ 4,590,057	\$ 1,907,882
General District wide Safety and Alternative Energy Solutions	\$ 3,778,973	\$ 2,561,720
Total Estimated Cost	\$ 53,100,000	\$ 19,079,741

<sup>\*</sup> The District Office Amount for the 2006 Bond includes approximately \$450,000 for Personnel management costs and the fees for bond sales.